

TEST REPORT

 Report No.:
 HC40053B/2020

 Page:
 1
 of
 12

 Date:
 May 28, 2020

VECOW CO., LTD. 3F., NO.10, JIANKANG RD., ZHONGHE DIST., NEW TAIPEI CITY, TAIWAN

The following merchandise was submitted and identified by the vendor as:Product Description:High Performance SystemStyle/ Item No.:SPC-5600A(with Fan Bracket)/ No.1Quantity:Total 1 setTesting Period:Apr. 14, 2020 to Apr. 27, 2020

We have tested the submitted sample(s) as requested and the following results were obtained: <u>Test Required:</u> (According to client's test specification, please see following sheets in detail.)

- 1. Low Temperature Test
- 2. High Temperature Test
- 3. Random Vibration Test
- 4. Mechanical Shock Test

Test Results : -PLEASE SEE ATTACHED SHEETS-

* HC40053A/2020, dated on May 25, 2020, is hereby canceled and replaced by HC40053B/2020.

Signed for and on behalf of SGS TAIWAN Ltd.

Allen Wang Asst. Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com.tw/Terms-and-Conditions</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/en/terms-and-conditions</u> and, for electronic format issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com

Member of SGS Group



Report No.:	HC4	40053B/2	2020
Page:	2	of	12

Reliability Laboratory

ow Temperature Test.

Pro

1. Low Temperature Test:				
Test Equipment:				
Name		Brand	Model	Serial No.
Programmable Temperature an	d Humidity Chamber	GIANT FORCE	GTH-800-40-CP-AR	MAA2003-004
Lab Environmental Condi	tions:			
Ambient temperature:	(25 ± 3) °C			
Relative humidity:	<u>(55 ± 20) % RH</u>			
Test Location:	No.17, Wu Chyuan	8th Road, New Ta	<u>aipei Industrial Park, W</u>	/uKu District,
	New Taipei City, Ta	<u>aiwan.</u>		
Test Method/ Specification	<u>1:</u>			
Sample condition:	Operating (execute	"BurnIn Test")		
Test Temperature:	<u>-25 °C</u>			
Duration:	<u>16 hours</u>			

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC	40053B/2	2020
Page:	3	of	12

Specimen:

Style/ Item No .: Quantity:

SPC-5600A(with Fan Bracket)/ No.1 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance Check (Visual Check)	Functional check
SPC-5600A (with Fan Bracket)/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC ²	40053B/2	2020
Page:	4	of	12

Reliability Laboratory

2. High Temperature Test:

Test Equipment:				
Name	2	Brand	Model	Serial No.
Programmable Temperature a	nd Humidity Chamber	GIANT FORCE	GTH-800-40-CP-AR	MAA2003-004
Lab Environmental Cond	itions:			
Ambient temperature:	(25 ± 3) °C			
Relative humidity:	<u>(55 ± 20) % RH</u>			
Test Location:	<u>No.17, Wu Chyuan</u>	8th Road, New Ta	aipei Industrial Park, V	VuKu District,
	New Taipei City, Ta	aiwan.		
Test Method/ Specification	on:			
Sample condition:	Operating (execute	"BurnIn Test")		
Test Temperature:	<u>60 °C</u>			
Test humidity:	<u>95 % RH</u>			
Duration:	16 hours			

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC	40053B/2	2020
Page:	5	of	12

Specimen:

Style/ Item No .: Quantity:

SPC-5600A(with Fan Bracket)/ No.1 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance Check (Visual Check)	Functional check
SPC-5600A (with Fan Bracket)/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC ²	40053B/2	2020
Page:	6	of	12

3. Random Vibration Test:

Test Equipment:

Name	Brand	Model	Serial No.
Vibration Test System	IMV	J260/SA7M	14101899
Controller	IMV	K2	14101899
Control Accelerometer	PCB	353B34	139174
Vibration Tester	King Design	EM-5000F2K-75N600	WR109237101
Controller	Crystal	spider	1001664
Control Accelerometer	WR	793-6	A4632

Lab Environmental Conditions: Ambient temperature: (25 ± 3) °C Amb

ient humidity:	(55	± 2	(0)	6 RH
	(- / /	• = == =

Test Location:	No.31/33 Wu Chyuan Road, New Taipei Industrial Park, WuKu District,
	New Taipei City, Taiwan

Test Method/ Specification:

	Frequency	Left Slope	PSD
Frequency:	<u>(5 ~ 500) Hz</u>		
Wave form:	Random		
Sample condition:	Operating (exec	ute "BurnIn Test")
Test Method:	<u>IEC 60068-2-64</u>	4, Edition 2.0: 200	8

Frequency (Hz)	Left Slope (dB/Oct.)	PSD (g ² /Hz)	Right Slope (dB/Oct.)	
5		0.05	0	
500	0	0.05		
⇐> equivalent to 5.0 G _{rms}				

Direction: Duration:

X, Y, Z axes 30 minutes/ axis

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路31號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC	40053B/2	2020
Page:	7	of	12

Specimen:

Style/ Item No.: Quantity:

SPC-5600A(with Fan Bracket)/ No.1 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
SPC-5600A (with Fan Bracket)/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC4	40053B/2	2020
Page:	8	of	12

4. Mechanical Shock Test:

Test Equipment:

Name	Brand	Model	Serial No.
Shock Test System	LANSMONT	95/ 115D	M-17656
Data Acquisition & Analysis System	LANSMONT	TP4 8A-CH SML 1115-001	1115-001
ICP Accelerometer	PCB	353M288	190563

<u>Lab Environmental Conditions:</u> Ambient temperature: (25 ± 3)

Ambient temperature: $(25 \pm 3) \degree C$ Ambient humidity: $(55 \pm 20) \% RH$

Test Location:

No.33, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan

Test Method/ Specification:

Test Method:	IEC 60068-2-27, Edition 4.0: 2008
Sample condition:	Operating (execute "BurnIn Test")
Pulse shape:	Half-sine
Acceleration:	<u>50 g</u>
Pulse duration:	<u>11 ms</u>
Shock direction:	<u>6 faces ($\pm X$, $\pm Y$, $\pm Z$ axes)</u>
No. of shock:	3 shocks/ axis (total 18 shocks)

• Examine the appearance of specimen(s) by visual check and perform functional check after this test.

• Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/en/terms-and-conditions/terms-end-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com

Member of SGS Group



TEST REPORT

Report No.:	HC ₄	40053B/2	2020
Page:	9	of	12

Specimen:

Style/ Item No.: Quantity:

SPC-5600A(with Fan Bracket)/ No.1 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
SPC-5600A (with Fan Bracket)/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.




Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No .:	HC4	0053B/2	2020
Page:	10	of	12

Test Photos:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC4	0053B/2	2020
Page:	11	of	12

Test Photos--Continued:

7. Random Vibration Test: Z axis	8. Mechanical Shock Test: +X axis
9. Mechanical Shock Test: -X axis	10. Mechanical Shock Test: +Y axis
11. Mechanical Shock Test: -Y axis	12. Mechanical Shock Test: +Z axis

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/ 新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC40053B/2020		
Page:	12	of	12

Test Photos--Continued:

13. Mechanical Shock Test: -Z axis	14. Functional check

The End of Test Report

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權略 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558